



Commercial Vehicle Inspection Report

Decal Number: FS83135
Decal Expiry Date: 2023-Jul-31
Inspection Number: 20177113

Inspection Result: **PASS**

Facility: METRO TRUCK AND TRAILER REPAIR / S11850
Inspector: SIDHU, PAWANPREET / 201923
Work Order Number:
Inspection Type: Complete
Inspection Class: Class 3 - Trailer and Semi-Trailer
Inspection Reason: Annual
Inspection Start Date/Time: 2022-Jul-13 08:47 AM
Inspection Complete Date/Time: 2022-Jul-13 11:20 AM

Vehicle Jurisdiction: British Columbia
Registration Number: 12733936
VIN: 1UYVS2535K3522804
Plate Number: 18117K
Licenced GVW (kg): 999999
Vehicle Year: 2019
Make: UTILITY
Brake Type: Air
Fuel Type:
Odometer:
Hub Odometer:
Body Style: Van Trailer
Model:
Unit/Fleet Number: 53232
Owner/Lessee Name: HAP, HAP TRUCKING LTD.
Address: 7954 WEBSTER RD
City: Delta
Province/State: British Columbia
Postal Code/ZIP: V4G1G6
Country: Canada

	Result	Comment
Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Not Applicable	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Repaired (same day)	QUICK RELEASE REPLACED
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Not Applicable	
Section 5 - Instruments and Auxiliary Equipment	Not Applicable	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Repaired (same day)	GLADHAND SEALS RELPLACED
Section 11 - Other Vehicle Components	Not Applicable	

Air Brake Chamber Type, Size and Push Rod Stroke Measurements (mm)

Axles (front)	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	32	32
2	Clamp	30	Automatic	32	32

Comment:

Tire Tread Depth (mm)

Axles (front)	Outer Left	Inner left	Inner Right	Outer Right	Steering Axle?
1	9.5	10.3	10.3	10.3	
2	9.5	10.3	8.7	9.5	

Comment:

Air Brake Camshaft Rotation Measurement (degrees)

Axles (front)	Left (degrees)	Right (degrees)
1	40	41
2	42	45

Comment:

Brake Lining/Pad Measurement (mm)

Axles (front)	Lining/Pad	Left	Right
1	Lining (Shoe)	19	20
2	Lining (Shoe)	19	18

Comment:

Rotor Thickness or Drum Inside Diameter Measurement (mm)

Axles (front)	Rotor/Drum	Left	Right
1	Drum	0.00	0.00
2	Drum	0.00	0.00

Comment:

Inspection Comments:

Has this Vehicle been road tested? No When?

Inspector Name: SIDHU, PAWANPREET

Signature:

Name of the person who did the road test:

This Inspection Report was submitted to CVSE on 2022-Jul-13 02:22 PM

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/M.P. at the Commercial Vehicle Safety Enforcement.

CVSE0014

7/13/2022 2:22:28 PM