



# Commercial Vehicle Inspection Report

Decal Number: FS83144  
Decal Expiry Date: 2023-Jul-31  
Inspection Number: 20180528

Inspection Result: **PASS**

Facility: METRO TRUCK AND TRAILER REPAIR / S11850  
Inspector: SIDHU, PAWANPREET / 201923  
Work Order Number:  
Inspection Type: Complete  
Inspection Class: Class 3 - Trailer and Semi-Trailer  
Inspection Reason: Annual  
Inspection Start Date/Time: 2022-Jul-16 02:23 AM  
Inspection Complete Date/Time: 2022-Jul-16 10:44 AM

Vehicle Jurisdiction: British Columbia  
Registration Number: 12724996  
VIN: 5V8VA53B3KM900011  
Plate Number: 83801U  
Licensed GVW (kg): 999999  
Vehicle Year: 2019  
Make: VANGUARD  
Brake Type: Air  
Fuel Type:  
Odometer:  
Hub Odometer:  
Body Style: Van Trailer  
Model:  
Unit/Fleet Number: 53326  
Owner/Lessee Name: HAP, HAP TRUCKING LTD.  
Address: 7954 WEBSTER ROAD  
City: Delta  
Province/State: British Columbia  
Postal Code/ZIP: V4G 1G6  
Country: Canada

	Result	Comment
Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Not Applicable	
Section 2 - Suspension	Repaired (same day)	AXLE 2 R/S SHOCK REPLACED
Section 3 - Brake System	Repaired (same day)	ALL AXLE BRAKES,S-CAM & SLACKS REPLACED
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Not Applicable	
Section 5 - Instruments and Auxiliary Equipment	Not Applicable	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	

Axles (front)	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	32	32
2	Clamp	30	Automatic	32	32
3	Clamp	30	Automatic	32	32

Comment:

Axles (front)	Outer Left	Inner Left	Inner Right	Outer Right	Steering Axle?
1	6.4	11.9	13.5	13.5	
2	12.7	9.5	8.7	9.5	
3	7.9	9.5	7.9	11.9	

Comment:

Axles (front)	Left (degrees)	Right (degrees)
1	0	0
2	0	0
3	0	0

Comment:

Axles (front)	Lining/Pad	Left	Right
1	Lining (Shoe)	21	21
2	Lining (Shoe)	21	21
3	Lining (Shoe)	21	21

Comment:

Axles (front)	Rotor/Drum	Left	Right
1	Drum	419.10	419.10
2	Drum	419.10	419.10
3	Drum	419.10	419.10

Comment:

Inspection Comments:

Has this Vehicle been road tested? No When?

Inspector Name: SIDHU, PAWANPREET

Signature:

Name of the person who did the road test:

This Inspection Report was submitted to CVSE on 2022-Jul-16 10:46 AM

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

### NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/MP at the Commercial Vehicle Safety Enforcement

CVSE0014

7/16/2022 10:46:19 AM