

Commercial Vehicle Inspection Report

Decal Number: Decal Expiry Date: Inspection Number:

GB56744 2025-Mar-31 20841480

Inspection Result:

Steering

METRO TRUCK AND TRAILER FACILITY:

REPAIR / S11850

BAGRI, AMRITPAL / 300086

INSP. TYPE: INSP. CLASS:

Class 3 - Trailer and Semi-Trailer

INSP. START:

2024-Mar-03 08:40 AM PST

NSPECTOR:

006529

INSP. REASON:

Annual

INSP. COMPLETE:

2024-Mar-04 06:00 AM PST

NORK ORDER #:

VEHICLE JUR:

VEHICLE YEAR:

PLATE #:

VIAKE:

WODEL:

British Columbia 33204U

LICENCED GVW(kg): 999999 2017 UTILITY REGI: 11957274 UNIT/FLEET#: 53204 BODY STYLE:

Van Trailer

Complete

VIN: OWNER/LESSEE NAME: ADDRESS:

1UYVS2538H7059414 HAPT, HAP TRUCKING LTD 7954 webster rd, 7954 webster rd

Delta, British Columbia V4G1G6, Canada

HUB ODOMETER: **BRAKE TYPE:** Air

FUEL TYPE:

ODOMETER:

Vehicle Identification (VIN)

Section 1 - Power Train Section 2 - Suspension

Not Applicable Repaired (same day)

axle 2 right side shock replaced

Section 3 - Brake System Section 3A - Air Brakes Section 3H - Hydraulic Brakes

Section 4 - Steering Section 5 - Instruments and Auxiliary

Equipment Section 6 - Lamps

Section 7 - Electrical System

Passed Section 8 - Frame and Body

Passed

Passed

Passed

Passed

Passed

Not Applicable

Not Applicable

Not Applicable

Repaired (same day) document holder replaced

Section 9A - Tires Section 9B - Wheels Passed Section 10 - Coupling Devices Passed Section 11 - Other Vehicle Components Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Tire Tread Depth (mm)

Axies	iype	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R
1	Clamp	30	Automatic	35	35	10.3	9.5	9.5	8.7
2	Clamp	30	Automatic	35	35	11.9	11.9	10.3	11.9

Comment: Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right	
1	62	45	Lining (Shoe)	17	17	Drum	419.85	419.79	
2	60	75	Lining (Shoe)	16	16	Drum	419.99	420.00	
Comment:			Comment:			Comment:			

nspection Comments:

las this Vehicle been road tested? nspector: BAGRI, AMRITPAL

No

Road Test Date: Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2024-Mar-04 09:44 AM PST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.