

Commercial Vehicle Inspection Report

Decal Number: Decal Expiry Date: Inspection Number: GB27891 2025-Jan-31 20791112

Inspection Result:

Steering

FACILITY: METRO TRUCK AND TRAILER

REPAIR / S11850

BAGRI, AMRITPAL / 300086

005942

INSP. TYPE: INSP. CLASS:

INSP. REASON:

Complete

Annual

12103637

53207

Class 3 - Trailer and Semi-Trailer

INSP. START: INSP. COMPLETE: 2024-Jan-15 04:00 PM PST 2024-Jan-16 06:30 AM PST

NSPECTOR: **NORK ORDER #:**

British Columbia

39987U JCENCED GVW(kg): 999999

VEHICLE YEAR: 2017 WAKE: **GREAT DANE**

VEHICLE JUR:

PLATE #:

WODEL:

UNIT/FLEET#: **BODY STYLE:**

REGI:

Van Trailer

ODOMETER: HUB ODOMETER:

BRAKE TYPE: Air **FUEL TYPE:**

VIN: OWNER/LESSEE NAME:

ADDRESS:

1GRAP0622HT108158 HAPT, HAP TRUCKING LTD

Delta, British Columbia

7954 webster rd, 7954 webster rd

V4G1G6, Canada

Vehicle Identification (VIN) Section 1 - Power Train Section 2 - Suspension Section 3 - Brake System Section 3A - Air Brakes Section 3H - Hydraulic Brakes Section 4 - Steering

Section 5 - Instruments and Auxiliary Equipment

Section 6 - Lamps Section 7 - Electrical System Section 8 - Frame and Body Section 9A - Tires

Section 9B - Wheels Section 10 - Coupling Devices Section 11 - Other Vehicle Components Passed

Not Applicable Passed Passed Passed

Not Applicable Not Applicable

Not Applicable

Passed Passed Passed Passed Passed Passed

Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Tire Tread Depth (mm) Axles Size Type Slack Adi. Left Right Outer L Inner L Inner R Outer R 30 1 Clamp Automatic 33 33 6.4 6.4 11.1 11.1 2 Clamp 30 Automatic 33 32 14.3 14.3 9.5 11.1

Comment:

Air Brake Camshaft Rotation (degrees) Brake Lining/Pad (mm) Rotor Thickness or Drum Inside Diameter (mm) Axles Left Right Lining/Pad Left Right Rotor/Drum Left Right 77 80 Lining (Shoe) 13 12 0.00 Drum 0.00 2 85 50 Lining (Shoe) 12 17 Drum 0.00 420.18 Comment: Comment: Comment:

Comment:

nspection Comments:

las this Vehicle been road tested? BAGRI, AMRITPAL nspector:

No **Road Test Date:**

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2024-Jan-16 09:10 AM PST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.