



# Commercial Vehicle Inspection Report

Decal Number: GB27872  
Decal Expiry Date: 2025-Jan-31  
Inspection Number: 20777821

Inspection Result:  
**PASS**

**FACILITY:** METRO TRUCK AND TRAILER REPAIR / S11850  
**INSPECTOR:** BAGRI, AMRITPAL / 300086  
**WORK ORDER #:** ~~006309~~ 005927  
**INSP. TYPE:** Complete  
**INSP. CLASS:** Class 3 - Trailer and Semi-Trailer  
**INSP. REASON:** Annual  
**INSP. START:** 2024-Jan-02 01:10 PM PST  
**INSP. COMPLETE:** 2024-Jan-02 03:00 PM PST

**VEHICLE JUR:** British Columbia  
**PLATE #:** 39980U  
**PERMITTED GVW(kg):** 999999  
**VEHICLE YEAR:** 2017  
**MAKE:** GREAT DANE  
**MODEL:**  
**REGI:** 12109701  
**UNIT/FLEET#:** 53210  
**BODY STYLE:** Van Trailer  
**ODOMETER:**  
**HUB ODOMETER:**  
**BRAKE TYPE:** Air  
**FUEL TYPE:**  
**VIN:** 1GRAP0622HT108161  
**OWNER/LESSEE NAME:** HAPT, HAP TRUCKING LTD  
**ADDRESS:** 7954 webster rd, 7954 webster rd  
Delta, British Columbia  
V4G1G6, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Repaired (same day) left side marker light replaced
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	33	34	12.7	12.7	8.7	7.9	
2	Clamp	30	Automatic	35	32	7.1	8.7	8.7	9.5	
<b>Comment:</b>				<b>Comment:</b>						

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right	
1	45	45	Lining (Shoe)	18	18	Drum	0.00	0.00	
2	52	60	Lining (Shoe)	16	16	Drum	0.00	0.00	
<b>Comment:</b>			<b>Comment:</b>			<b>Comment:</b> ALL DUST SHIELD REMOVED			

**Inspection Comments:**  
**Has this Vehicle been road tested?** No  
**Inspector:** BAGRI, AMRITPAL  
**Road Test Date:**  
**Signature:**   
**Road Tester:**

This Inspection Report was submitted to CVSE on 2024-Jan-03 08:13 AM PST  
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

**NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.**

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement