



# Commercial Vehicle Inspection Report

Decal Number: GB27858  
Decal Expiry Date: 2024-Dec-31  
Inspection Number: 20765945

Inspection Result:  
**PASS**

**FACILITY:** METRO TRUCK AND TRAILER REPAIR / S11850  
**INSPECTOR:** BAGRI, AMRITPAL / 300086  
**WORK ORDER #:** 005911  
**INSP. TYPE:** Complete  
**INSP. CLASS:** Class 3 - Trailer and Semi-Trailer  
**INSP. REASON:** Annual  
**INSP. START:** 2023-Dec-21 10:00 AM PST  
**INSP. COMPLETE:** 2023-Dec-21 12:00 PM PST

**VEHICLE JUR:** British Columbia  
**PLATE #:** 51085K  
**LICENSED GVW(kg):** 999999  
**VEHICLE YEAR:** 2017  
**MAKE:** GREAT DANE  
**MODEL:**  
**REGI:** 12294165  
**UNIT/FLEET#:** 53212  
**BODY STYLE:** Van Trailer  
**ODOMETER:**  
**HUB ODOMETER:**  
**BRAKE TYPE:** Air  
**FUEL TYPE:**  
**VIN:** 1GRAA0627HD469042  
**OWNER/LESSEE NAME:** HAPT, HAP TRUCKING LTD  
**ADDRESS:** 7954 webster rd, 7954 webster rd  
Delta, British Columbia  
V4G1G6, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)					Steering
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	
1	Clamp	30	Automatic	32	32	7.9	8.7	9.5	9.5
2	Clamp	30	Automatic	32	32	8.7	9.5	7.1	7.9

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	30	25	Lining (Shoe)	19	21	Drum	0.00	0.00
2	30	32	Lining (Shoe)	19	19	Drum	0.00	0.00

Comment: all axle dust shield remove and re install

**Inspection Comments:**  
Has this Vehicle been road tested? No  
**Inspector:** BAGRI, AMRITPAL  
**Road Test Date:**  
**Signature:**   
**Road Tester:**

This Inspection Report was submitted to CVSE on 2023-Dec-21 02:20 PMPST  
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.