

Commercial Vehicle Inspection Report

Decal Number: **FY74311**
 Decal Expiry Date: **2024-Aug-31**
 Inspection Number: **20616992**

Inspection Result:
PASS

FACILITY: METRO TRUCK AND TRAILER REPAIR / S11850 **INSP. TYPE:** Complete **INSP. START:** 2023-Aug-14 02:15 PM PDT
INSPECTOR: BAGRI, AMRITPAL / 300086 **INSP. CLASS:** Class 3 - Trailer and Semi-Trailer **INSP. COMPLETE:** 2023-Aug-14 04:00 PM PDT
WORK ORDER #: 00513 **INSP. REASON:** Annual

VEHICLE JUR: British Columbia **REGI:** 12290393 **VIN:** 1GRAA0622HD469045
PLATE #: 56814U **UNIT/FLEET#:** 53215 **OWNER/LESSEE NAME:** hap, hap trucking ltd
PERMITTED GVW(kg): 999999 **BODY STYLE:** Van Trailer **ADDRESS:** 7954 webster road, 7954 webster road
VEHICLE YEAR: 2017 **ODOMETER:** Delta, British Columbia
MAKE: GREAT DANE **HUB ODOMETER:** V4G1G6, Canada
MODEL: **BRAKE TYPE:** Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) axle 2 both side s cam tube kit replaced
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	32	32	12.7	12.7	12.7	12.7	
2	Clamp	30	Automatic	32	32	12.7	12.7	12.7	12.7	
Comment:				Comment:						

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right	
1	80	75	Lining (Shoe)	15	16	Drum	0.00	0.00	
2	35	35	Lining (Shoe)	21	20	Drum	0.00	0.00	
Comment:			Comment:			Comment:			

Inspection Comments:

Has this Vehicle been road tested? No **Road Test Date:** **Road Tester:**
Inspector: BAGRI, AMRITPAL **Signature:** 

This Inspection Report was submitted to CVSE on 2023-Aug-14 05:19 PM PDT
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.