



Commercial Vehicle Inspection Report

Decal Number: GC55857
Decal Expiry Date: 2025-Jun-30
Inspection Number: 20960919

Inspection Result:
PASS


CILITY: METRO TRUCK AND TRAILER REPAIR / S11850
SPECTOR: BAGRI, AMRITPAL / 300086
ORK ORDER #: 007522
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual
INSP. START: 2024-Jun-07 09:00 AM PDT
INSP. COMPLETE: 2024-Jun-07 01:10 PM PDT

EHICLE JUR: British Columbia
ATE #: 84148K
ENCED GVW(kg): 999999
EHICLE YEAR: 2017
AKE: GREAT DANE
ODEL:
REGI: 12294164
UNIT/FLEET#: 53216
BODY STYLE: Van Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 1GRAA0624HD469046
OWNER/LESSEE NAME: HAPT, HAP TRUCKING LTD
ADDRESS: 7954 webster rd, 7954 webster rd
Delta, British Columbia
V4G1G6, Canada

ehicle Identification (VIN)	Passed
ection 1 - Power Train	Not Applicable
ection 2 - Suspension	Passed
ection 3 - Brake System	Repaired (same day) axle 1 left and axle 2 both side brake and drum replaced
ection 3A - Air Brakes	Passed
ection 3H - Hydraulic Brakes	Not Applicable
ection 4 - Steering	Not Applicable
ection 5 - Instruments and Auxillary equipment	Not Applicable
ection 6 - Lamps	Passed
ection 7 - Electrical System	Passed
ection 8 - Frame and Body	Passed
ection 9A - Tires	Passed
ection 9B - Wheels	Passed
ection 10 - Coupling Devices	Passed
ection 11 - Other Vehicle Components	Not Applicable

Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)					Steering	
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	
1	Clamp	30	Automatic	35	35	5.6	8.7	7.9	7.9	
2	Clamp	30	Automatic	37	37	8.7	8.7	11.9	7.9	

Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	25	65	Lining (Shoe)	21	18	Drum	419.10	419.36
2	25	25	Lining (Shoe)	21	21	Drum	419.10	419.10

Inspection Comments:
Is this Vehicle been road tested? No
Inspector: BAGRI, AMRITPAL
Road Test Date:
Signature: 
Road Tester:

This Inspection Report was submitted to CVSE on 2024-Jun-07 01:14 PM PDT
Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.