

<b>FACILITY:</b>	SANDHER TRUCK & TRAILER REPAIR LTD. / S15370	<b>INSP. TYPE:</b>	Complete	<b>INSP. START:</b>	2023-Nov-17 10:00 AM PST
<b>INSPECTOR:</b>	SANDHAR, DAVINDERJIT / 202087	<b>INSP. CLASS:</b>	Class 3 - Trailer and Semi-Trailer	<b>INSP. COMPLETE:</b>	2023-Nov-17 11:30 AM PST
<b>WORK ORDER #:</b>		<b>INSP. REASON:</b>	Annual		

<b>VEHICLE JUR:</b>	British Columbia	<b>REGI:</b>	12364254	<b>VIN:</b>	1UYVS2537J7349813
<b>PLATE #:</b>	26440K	<b>UNIT/FLEET#:</b>	53219	<b>OWNER/LESSEE NAME:</b>	HAP, ENTERPRISES LTD
<b>LICENCED GVW(kg):</b>	999999	<b>BODY STYLE:</b>	Van Trailer	<b>ADDRESS:</b>	7954 WEBSTER RD
<b>VEHICLE YEAR:</b>	2018	<b>ODOMETER:</b>			Delta, British Columbia
<b>MAKE:</b>	UTILITY	<b>HUB ODOMETER:</b>			v4g1g6, Canada
<b>MODEL:</b>		<b>BRAKE TYPE:</b>	Air		
		<b>FUEL TYPE:</b>			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	35	38
2	Clamp	30	Automatic	37	39
<b>Comment:</b>					

Outer L	Inner L	Inner R	Outer R	Steering
12.7	12.7	14.3	14.3	
9.5	10.3	7.9	7.9	
<b>Comment:</b>				

Axles	Left	Right
1	85	30
2	25	85
<b>Comment:</b>		

Lining/Pad	Left	Right
Lining (Shoe)	16	19
Lining (Shoe)	19	16
<b>Comment:</b>		

Rotor/Drum	Left	Right
Drum		
Drum		
<b>Comment:</b> Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

**Inspection Comments:**

Has this Vehicle been road tested?  No      **Road Test Date:** \_\_\_\_\_      **Road Tester:** \_\_\_\_\_

**Inspector:** SANDHAR, DAVINDERJIT      **Signature:** \_\_\_\_\_

This Inspection Report was submitted to CVSE on 2023-Nov-17 04:42 PM PST  
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.