



Commercial Vehicle Inspection Report

Decal Number: GD39108
Decal Expiry Date: 2025-Jul-31
Inspection Number: 20996553

Inspection Result:
PASS

FACILITY: METRO TRUCK AND TRAILER REPAIR / S11850
INSPECTOR: BAGRI, AMRITPAL / 300086
WORK ORDER #: 008108
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual
INSP. START: 2024-Jul-08 01:00 PM PDT
INSP. COMPLETE: 2024-Jul-08 04:09 PM PDT

VEHICLE JUR: British Columbia
PLATE #: 70897K
LICENCED GVW(kg): 999999
VEHICLE YEAR: 2019
MAKE: UTILITY
MODEL:
REGI: 12733743
UNIT/FLEET#: 53231
BODY STYLE: Van Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 1UYVS2533K3522803
OWNER/LESSEE NAME: HAPT, HAP TRUCKING LTD
ADDRESS: 7954 webster rd, 7954 webster rd Delta, British Columbia V4G1G6, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) axle 2 left side brake chamber air line replaced
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Repaired (same day) amber replaced
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)					Steering
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R
1	Clamp	30	Automatic	35	35	9.5	9.5	14.3	13.5
2	Clamp	30	Automatic	36	35	8.7	8.7	7.9	7.1
Comment:				Comment:					

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	75	85	Lining (Shoe)	14	14	Drum	419.60	419.65
2	80	55	Lining (Shoe)	13	17	Drum	419.56	419.25
Comment:			Comment:			Comment:		

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: BAGRI, AMRITPAL
Road Test Date: [Signature]
Road Tester:

This Inspection Report was submitted to CVSE on 2024-Jul-08 04:13 PMPDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.