



# Commercial Vehicle Inspection Report

Decal Number: **GD39110**  
 Decal Expiry Date: **2025-Jul-31**  
 Inspection Number: **20998329**

Inspection Result:  
**PASS**

**FACILITY:** METRO TRUCK AND TRAILER REPAIR / S11850  
**INSPECTOR:** BAGRI, AMRITPAL / 300086  
**WORK ORDER #:** 008121

**INSP. TYPE:** Complete  
**INSP. CLASS:** Class 3 - Trailer and Semi-Trailer  
**INSP. REASON:** Annual

**INSP. START:** 2024-Jul-09 10:00 AM PDT  
**INSP. COMPLETE:** 2024-Jul-10 07:00 AM PDT

**VEHICLE JUR:** British Columbia  
**PLATE #:** 61795K  
**LICENSED GVW(kg):** 999999  
**VEHICLE YEAR:** 2019  
**MAKE:** UTILITY  
**MODEL:**

**REGI:** 12733936  
**UNIT/FLEET#:** 53232  
**BODY STYLE:** Van Trailer  
**ODOMETER:**  
**HUB ODOMETER:**  
**BRAKE TYPE:** Air  
**FUEL TYPE:**

**VIN:** 1UYVS2535K3522804  
**OWNER/LESSEE NAME:** HAPT, HAP TRUCKING LTD  
**ADDRESS:** 7954 webster rd, 7954 webster rd  
 Delta, British Columbia  
 V4G1G6, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) axle 1 and left side brake and drum replaced
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxillary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Repaired (same day) axle 2 right side tire replaced
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	34	34	9.5	8.7	9.5	11.1	
2	Clamp	30	Automatic	35	36	8.7	9.5	15.1	15.1	
<b>Comment:</b>				<b>Comment:</b>						

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	25	30	Lining (Shoe)	21	20	Drum	419.10	419.30
2	25	32	Lining (Shoe)	21	20	Drum	419.10	419.20
<b>Comment:</b>			<b>Comment:</b>			<b>Comment:</b>		

**Inspection Comments:**  
 Has this Vehicle been road tested?  No  
**Inspector:** BAGRI, AMRITPAL  
**Road Test Date:** \_\_\_\_\_  
**Signature:**   
**Road Tester:** \_\_\_\_\_

This Inspection Report was submitted to CVSE on 2024-Jul-10 07:29 AM PDT  
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.