



Commercial Vehicle Inspection Report

Decal Number: GB56778
Decal Expiry Date: 2025-Apr-30
Inspection Number: 20877910

Inspection Result:
PASS

FACILITY: METRO TRUCK AND TRAILER REPAIR / S11850
INSPECTOR: BAGRI, AMRITPAL / 300086
WORK ORDER #: 007003
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual
INSP. START: 2024-Apr-03 04:00 PM PDT
INSP. COMPLETE: 2024-Apr-04 06:40 AM PDT

VEHICLE JUR: British Columbia
PLATE #: 58492K
PERMITTED GVW(kg): 0
VEHICLE YEAR: 2024
MAKE: UTILITY
MODEL:
REGI: 14300512
UNIT/FLEET#: 53236
BODY STYLE: Van Trailer
ODOMETER:
HUB ODOMETER: 75915 KM
BRAKE TYPE: Air
FUEL TYPE:
VIN: 1UYVS2531R7028832
OWNER/LESSEE NAME: HAPT, HAP TRUCKING LTD
ADDRESS: 7954 webster rd, 7954 webster rd
Delta, British Columbia
V4G1G6, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	35	35	8.7	8.7	8.7	8.7	
2	Clamp	30	Automatic	35	35	7.9	7.9	7.9	8.7	

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	40	40	Lining (Shoe)	20	20	Drum	419.15	419.18
2	40	40	Lining (Shoe)	21	20	Drum	419.12	419.18

Inspection Comments:
Has this Vehicle been road tested? No
Inspector: BAGRI, AMRITPAL
Road Test Date:
Signature: 
Road Tester:

This Inspection Report was submitted to CVSE on 2024-Apr-04 07:39 AM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.