



# Commercial Vehicle Inspection Report

Decal Number: GD39128  
Decal Expiry Date: 2025-Jul-31  
Inspection Number: 21010334

Inspection Result:  
**PASS**

**FACILITY:** METRO TRUCK AND TRAILER REPAIR / S11850  
**INSPECTOR:** BAGRI, AMRITPAL / 300086  
**WORK ORDER #:** 007797  
**INSP. TYPE:** Complete  
**INSP. CLASS:** Class 3 - Trailer and Semi-Trailer  
**INSP. REASON:** Annual  
**INSP. START:** 2024-Jul-20 02:00 PM PDT  
**INSP. COMPLETE:** 2024-Jul-20 05:00 PM PDT

**VEHICLE JUR:** British Columbia  
**PLATE #:** 84123K  
**LICENCED GVW(kg):** 0  
**VEHICLE YEAR:** 2019  
**MAKE:** UTILITY  
**MODEL:**  
**REGI:** 12926425  
**UNIT/FLEET#:** 53242  
**BODY STYLE:** Van Trailer  
**ODOMETER:**  
**HUB ODOMETER:**  
**BRAKE TYPE:** Air  
**FUEL TYPE:**  
**VIN:** 1UYVS2536K7730909  
**OWNER/LESSEE NAME:** HAPT, HAP TRUCKING LTD  
**ADDRESS:** 7954 webster rd, 7954 webster rd  
Delta, British Columbia  
V4G1G6, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Repaired (same day) axle 1 and 2 right side air bag replaced
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxillary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Repaired (same day) axle 1 left side hub cap replaced
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	37	37	10.3	11.9	7.9	7.9	
2	Clamp	30	Automatic	36	36	7.9	8.7	7.1	7.1	
<b>Comment:</b>				<b>Comment:</b>						

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	75	70	Lining (Shoe)	15	15	Drum	419.76	419.65
2	75	80	Lining (Shoe)	14	14	Drum	419.95	419.79
<b>Comment:</b>			<b>Comment:</b>			<b>Comment:</b>		

**Inspection Comments:**  
**Has this Vehicle been road tested?** No  
**Inspector:** BAGRI, AMRITPAL  
**Road Test Date:**  
**Signature:**   
**Road Tester:**

This Inspection Report was submitted to CVSE on 2024-Jul-20 05:05 PMPDT  
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.