



Commercial Vehicle Inspection Report

Decal Number: GB55089
Decal Expiry Date: 2025-Mar-31
Inspection Number: 20840819

Inspection Result:
PASS

FACILITY: SANDHER TRUCK & TRAILER REPAIR LTD. / S15370
INSPECTOR: SANDHU, SIMRANJEET / 300113
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual

INSP. START: 2024-Mar-01 02:00 PM PST
INSP. COMPLETE: 2024-Mar-01 03:30 PM PST

VEHICLE JUR: British Columbia
PLATE #: 09807J
LICENCED GVW(kg): 0
VEHICLE YEAR: 2019
MAKE: UTILITY
MODEL:

REGI: 12926534
UNIT/FLEET#: 53243
BODY STYLE: Van Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 1UYVS2532K7730910
OWNER/LESSEE NAME: HAP, TRUCKING LTD
ADDRESS: 7954 WEBSTER RD
Delta, British Columbia
V4G1G6, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	34	33
2	Clamp	30	Automatic	35	34

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
10.3	10.3	9.5	9.5	
8.7	7.9	8.7	8.7	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	65	70
2	80	45

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	15	14
Lining (Shoe)	13	19

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: SANDHU, SIMRANJEET
Road Test Date:
Road Tester:
Signature: _____

This Inspection Report was submitted to CVSE on 2024-Mar-02 02:33 PM PST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.