

Commercial Vehicle Inspection Report

Decal Number: GC55803
 Decal Expiry Date: 2025-Apr-30
 Inspection Number: 20897805

Inspection Result:
PASS

FACILITY: METRO TRUCK AND TRAILER REPAIR / S11850
INSPECTOR: BAGRI, AMRITPAL / 300086
WORK ORDER #: 006989
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual
INSP. START: 2024-Apr-19 12:52 PM PDT
INSP. COMPLETE: 2024-Apr-19 02:53 PM PDT

VEHICLE JUR: British Columbia
PLATE #: 55724K
PERMITTED GVW(kg): 0
VEHICLE YEAR: 2024
MAKE: UTILITY
MODEL:
REGI: 14307168
UNIT/FLEET#: 53248
BODY STYLE: Van Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 1UYVS2539R7028836
OWNER/LESSEE NAME: HAPT, HAP TRUCKING LTD
ADDRESS: 7954 webster rd, 7954 webster rd Delta, British Columbia V4G1G6, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Repaired (same day) right side marker light replaced
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	32	32	7.9	7.9	7.9	7.1	
2	Clamp	30	Automatic	35	35	7.9	7.9	7.1	6.4	
Comment:				Comment:						

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right	
1	32	35	Lining (Shoe)	19	19	Drum	419.25	419.22	
2	35	38	Lining (Shoe)	19	19	Drum	419.22	419.28	
Comment:			Comment:			Comment:			

Inspection Comments:
 Has this Vehicle been road tested? No **Road Test Date:** _____ **Road Tester:** _____
Inspector: BAGRI, AMRITPAL **Signature:** 

This Inspection Report was submitted to CVSE on 2024-Apr-19 02:56 PM PDT
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.