

Commercial Vehicle Inspection Report

Decal Number: **FY74350**
 Decal Expiry Date: **2024-Sep-30**
 Inspection Number: **20639752**

Inspection Result:
PASS

FACILITY: METRO TRUCK AND TRAILER REPAIR / S11850
INSPECTOR: BAGRI, AMRITPAL / 300086
WORK ORDER #: 005215

INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual

INSP. START: 2023-Sep-02 12:40 PM PDT
INSP. COMPLETE: 2023-Sep-02 02:39 PM PDT

VEHICLE JUR: British Columbia
PLATE #: 70449J
PERMITTED GVW(kg): 0
VEHICLE YEAR: 2021
MAKE: HYUNDAI
MODEL:

REGI: 13493082
UNIT/FLEET#: 53259
BODY STYLE: Van Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 3H3V532C2MT088013
OWNER/LESSEE NAME: hap, hap trucking ltd
ADDRESS: 7954 webster road, 7954 webster road
 Delta, British Columbia
 V4G1G6, Canada

| Vehicle Identification (VIN) | Result |
|---|---|
| Section 1 - Power Train | Passed |
| Section 2 - Suspension | Not Applicable |
| Section 3 - Brake System | Passed |
| Section 3A - Air Brakes | Repaired (same day) axle 1 both side and axle 2 left side brake and drum replaced |
| Section 3H - Hydraulic Brakes | Passed |
| Section 4 - Steering | Not Applicable |
| Section 5 - Instruments and Auxiliary Equipment | Not Applicable |
| Section 6 - Lamps | Repaired (same day) abs light replaced |
| Section 7 - Electrical System | Passed |
| Section 8 - Frame and Body | Passed |
| Section 9A - Tires | Passed |
| Section 9B - Wheels | Passed |
| Section 10 - Coupling Devices | Passed |
| Section 11 - Other Vehicle Components | Not Applicable |

| Air Brake Chamber Type, Size and Push Rod Stroke (mm) | | | | Tire Tread Depth (mm) | | | | | | |
|---|-------|------|------------|-----------------------|-------|---------|---------|---------|---------|----------|
| Axles | Type | Size | Slack Adj. | Left | Right | Outer L | Inner L | Inner R | Outer R | Steering |
| 1 | Clamp | 30 | Automatic | 30 | 30 | 6.4 | 4.8 | 13.5 | 13.5 | |
| 2 | Clamp | 30 | Automatic | 30 | 34 | 7.1 | 7.9 | 11.9 | 11.9 | |
| Comment: | | | | Comment: | | | | | | |

| Air Brake Camshaft Rotation (degrees) | | | Brake Lining/Pad (mm) | | | Rotor Thickness or Drum Inside Diameter (mm) | | |
|---------------------------------------|------|-------|-----------------------|------|-------|--|--------|--------|
| Axles | Left | Right | Lining/Pad | Left | Right | Rotor/Drum | Left | Right |
| 1 | 25 | 25 | Lining (Shoe) | 21 | 21 | Drum | 419.10 | 419.10 |
| 2 | 25 | 80 | Lining (Shoe) | 21 | 14 | Drum | 419.10 | 0.00 |
| Comment: | | | Comment: | | | Comment: | | |

Inspection Comments:

Has this Vehicle been road tested? No **Road Test Date:** _____ **Road Tester:** _____

Inspector: BAGRI, AMRITPAL **Signature:** 

This Inspection Report was submitted to CVSE on 2023-Sep-02 03:47 PM PDT
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.