



Commercial Vehicle Inspection Report

Decal Number: GA26775
Decal Expiry Date: 2024-Nov-30
Inspection Number: 20732648

Inspection Result:
PASS

FACILITY: METRO TRUCK AND TRAILER REPAIR / S11850
INSPECTOR: BAGRI, AMRITPAL / 300086
WORK ORDER #: 005764
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual
INSP. START: 2023-Nov-22 07:27 AM PST
INSP. COMPLETE: 2023-Nov-23 07:00 AM PST

VEHICLE JUR: British Columbia
PLATE #: 78788J
PERMITTED GVW(kg): 0
VEHICLE YEAR: 2021
MAKE: HYUNDAI
MODEL:
REGI: 13482278
UNIT/FLEET#: 53260
BODY STYLE: Van Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 3H3V532C4MT088014
OWNER/LESSEE NAME: HAPT, HAP TRUCKING LTD
ADDRESS: 7954 webster rd, 7954 webster rd
Delta, British Columbia
V4G1G6, Canada

Vehicle Identification (VIN) Passed
Section 1 - Power Train Not Applicable
Section 2 - Suspension Passed
Section 3 - Brake System **Repaired (same day)** axle 2 left side brake and drum replaced
Section 3A - Air Brakes Passed
Section 3H - Hydraulic Brakes Not Applicable
Section 4 - Steering Not Applicable
Section 5 - Instruments and Auxiliary Equipment Not Applicable
Section 6 - Lamps Passed
Section 7 - Electrical System Passed
Section 8 - Frame and Body Passed
Section 9A - Tires **Repaired (same day)** axle 1 both side tire replaced
Section 9B - Wheels **Repaired (same day)** axle 1 right side wheel seal replaced
Section 10 - Coupling Devices Passed
Section 11 - Other Vehicle Components Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	32	32	14.3	14.3	14.3	14.3	
2	Clamp	30	Automatic	32	32	11.9	11.9	13.5	13.5	

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right	
1	35	35	Lining (Shoe)	19	19	Drum	419.50	419.95	
2	30	45	Lining (Shoe)	21	17	Drum	419.05	420.19	

Comment:

Inspection Comments:
Has this Vehicle been road tested? No
Inspector: BAGRI, AMRITPAL
Road Test Date:
Signature: 
Road Tester:

This Inspection Report was submitted to CVSE on 2023-Nov-23 09:28 AM PST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.