

Commercial Vehicle Inspection Report

Decal Number: **GB56749**
 Decal Expiry Date: **2025-Mar-31**
 Inspection Number: **20848384**

Inspection Result:
PASS

FACILITY: METRO TRUCK AND TRAILER REPAIR / S11850	INSP. TYPE: Complete	INSP. START: 2024-Mar-08 03:00 PM PST
INSPECTOR: BAGRI, AMRITPAL / 300086	INSP. CLASS: Class 3 - Trailer and Semi-Trailer	INSP. COMPLETE: 2024-Mar-09 08:00 AM PST
WORK ORDER #: 006809	INSP. REASON: Annual	

VEHICLE JUR: British Columbia	REGI: 13506482	VIN: 3H3V532C0MT650006
PLATE #: 60728J	UNIT/FLEET#: 53261	OWNER/LESSEE NAME: HAPT, HAP TRUCKING LTD
LICENSED GVW(kg): 0	BODY STYLE: Van Trailer	ADDRESS: 7954 webster rd, 7954 webster rd
VEHICLE YEAR: 2021	ODOMETER:	Delta, British Columbia
MAKE: HYUNDAI	HUB ODOMETER:	V4G1G6, Canada
MODEL:	BRAKE TYPE: Air	
	FUEL TYPE:	

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) axle 1 and 2 both side brake and drum replaced
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Repaired (same day) axle 1 right side tire fix
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	35	35	6.4	7.1	8.7	8.7	
2	Clamp	30	Automatic	35	35	8.7	8.7	8.7	8.7	
Comment:				Comment:						

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right	
1	25	25	Lining (Shoe)	21	21	Drum	419.10	419.10	
2	25	25	Lining (Shoe)	21	21	Drum	419.10	419.10	
Comment:			Comment:			Comment:			

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: _____ Road Tester: _____

Inspector: BAGRI, AMRITPAL Signature: 

This Inspection Report was submitted to CVSE on 2024-Mar-09 01:11 PM PST
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.