

Commercial Vehicle Inspection Report

Decal Number: **GB27802**
 Decal Expiry Date: **2024-Dec-31**
 Inspection Number: **20744633**

Inspection Result:
PASS

FACILITY: METRO TRUCK AND TRAILER REPAIR / S11850
INSPECTOR: BAGRI, AMRITPAL / 300086
WORK ORDER #: 005780
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual
INSP. START: 2023-Dec-02 08:15 AM PST
INSP. COMPLETE: 2023-Dec-02 10:15 AM PST

VEHICLE JUR: British Columbia
PLATE #: 55665K
PERMITTED GVW(kg): 0
VEHICLE YEAR: 2023
MAKE: WABASH
MODEL:
REGI: 14248068
UNIT/FLEET#: 53269
BODY STYLE: Van Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 1JVV532D2PL366566
OWNER/LESSEE NAME: HAPT, HAP TRUCKING LTD
ADDRESS: 7954 webster rd, 7954 webster rd
 Delta, British Columbia
 V4G1G6, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	32	32
2	Clamp	30	Automatic	31	31

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
8.7	8.7	8.7	7.1	
8.7	8.7	8.7	7.9	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	40	40
2	50	45

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	19	19
Lining (Shoe)	18	18

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum	420.05	420.80
Drum	420.54	420.58

Comment:

Inspection Comments:

Has this Vehicle been road tested? No

Inspector: BAGRI, AMRITPAL

Road Test Date:

Signature:



Road Tester:

This Inspection Report was submitted to CVSE on 2023-Dec-02 10:25 AM PST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSE0014

12/2/2023 10:25:22 AM PST