

## **Commercial Vehicle** Inspection Report

Decal Number: **Decal Expiry Date:** Inspection Number:

GB32038 2025-Feb-28 20814611

Inspection Result:

FACILITY:

A-1 PAUL'S TRAILER REPAIR / S4161

81137

FLYNN, DANIEL / 202245

INSP. TYPE: INSP. CLASS:

Complete

INSP. START:

2024-Feb-07 09:00 AM PST

INSPECTOR: WORK ORDER #:

INSP. REASON:

Class 3 - Trailer and Semi-Trailer Annual

INSP. COMPLETE:

2024-Feb-07 10:30 AM PST

VEHICLE JUR: PI ATF #

VEHICLE YEAR:

British Columbia

65339K LICENCED GVW(kg): 0 2024

REGI: UNIT/FLEET#:

BODY STYLE:

ODOMETER:

BRAKE TYPE:

**FUEL TYPE:** 

**HUB ODOMETER:** 

14360797 53275 Van Trailer VIN: OWNER/LESSEE NAME:

1JJV532D8RL426403 Hap Trucking Ltd, Hap Trucking Ltd

7954 Webster Rd

Delta, British Columbia V4G 1G6, Canada

MODEL:

MAKE: WARASH

Air

Vehicle Identification (VIN)

Section 1 - Power Train Section 2 - Suspension Section 3 - Brake System Section 3A - Air Brakes

Section 3H - Hydraulic Brakes Section 4 - Steering

Section 5 - Instruments and Auxiliary Equipment Section 6 - Lamps

Section 7 - Electrical System Section 8 - Frame and Body Section 9A - Tires

Section 9B - Wheels Section 10 - Coupling Devices Passed

Not Applicable Passed

Passed Passed Not Applicable

Not Applicable Not Applicable

Passed Passed Passed

Passed Passed Passed

Section 11 - Other Vehicle Components

Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles Туре Size Slack Adj. 30L 1 Clamp Automatic 2 Clamp 30L Automatic Left Right 35 34 36 35

Outer L Inner L 11 10 Comment:

Tire Tread Depth (mm)

Inner R 11 9

Comment:

Steering

Right

419.50

419.50

Comment:

Air Brake Camshaft Rotation (degrees) Axles Left Right 33 35 2 37 34 Comment:

Lining/Pad Lining (Shoe) Lining (Shoe) Comment:

Brake Lining/Pad (mm)

Left Right 21 21 21 21

Rotor Thickness or Drum Inside Diameter (mm) Rotor/Drum Left Drum 419.50 Drum 419.50

Outer R

10

9

**Inspection Comments:** 

Has this Vehicle been road tested? FLYNN, DANIEL Inspector:

Road Test Date: Signature:

11

11

This Inspection Report was submitted to CVSE on 2024-Feb-07 12:31 PM PST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement CVSE0014