



# Commercial Vehicle Inspection Report

Decal Number: GC55811  
Decal Expiry Date: 2025-May-31  
Inspection Number: 20915634

Inspection Result:  
**PASS**

**FACILITY:** METRO TRUCK AND TRAILER REPAIR / S11850  
**INSPECTOR:** BAGRI, AMRITPAL / 300086  
**WORK ORDER #:** 007036  
**INSP. TYPE:** Complete  
**INSP. CLASS:** Class 3 - Trailer and Semi-Trailer  
**INSP. REASON:** Annual  
**INSP. START:** 2024-May-02 02:00 PM PDT  
**INSP. COMPLETE:** 2024-May-03 06:00 AM PDT

**VEHICLE JUR:** British Columbia  
**PLATE #:** 65340K  
**LICENCED GVW(kg):** 0  
**VEHICLE YEAR:** 2024  
**MAKE:** WABASH  
**MODEL:**  
**REGI:** 14360803  
**UNIT/FLEET#:** 53276  
**BODY STYLE:** Van Trailer  
**ODOMETER:**  
**HUB ODOMETER:**  
**BRAKE TYPE:** Air  
**FUEL TYPE:**  
**VIN:** 1JJV532DXRL426404  
**OWNER/LESSEE NAME:** HAPT, HAP TRUCKING LTD  
**ADDRESS:** 7954 webster rd, 7954 webster rd  
Delta, British Columbia  
V4G1G6, Canada

<b>Vehicle Identification (VIN)</b>	Passed
<b>Section 1 - Power Train</b>	Not Applicable
<b>Section 2 - Suspension</b>	Passed
<b>Section 3 - Brake System</b>	Passed
<b>Section 3A - Air Brakes</b>	Not Applicable
<b>Section 3H - Hydraulic Brakes</b>	Not Applicable
<b>Section 4 - Steering</b>	Not Applicable
<b>Section 5 - Instruments and Auxiliary Equipment</b>	Passed
<b>Section 6 - Lamps</b>	Passed
<b>Section 7 - Electrical System</b>	Passed
<b>Section 8 - Frame and Body</b>	Passed
<b>Section 9A - Tires</b>	Passed
<b>Section 9B - Wheels</b>	Passed
<b>Section 10 - Coupling Devices</b>	Passed
<b>Section 11 - Other Vehicle Components</b>	Not Applicable

### Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30L	Automatic	35	35
2	Clamp	30L	Automatic	35	35

Comment:

### Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
7.9	7.9	7.9	7.9	
7.9	7.9	7.9	7.9	

Comment:

### Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	40	42
2	40	40

Comment:

### Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	20	19
Lining (Shoe)	19	20

Comment:

### Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum	419.25	419.25
Drum	419.25	419.25

Comment:

### Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Road Tester:

Inspector: BAGRI, AMRITPAL

Signature: 

This Inspection Report was submitted to CVSE on 2024-May-03 06:42 AM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

### NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSE0014

5/3/2024 6:42:04 AM PDT