

Commercial Vehicle Inspection Report

Decal Number: GC55808
Decal Expiry Date: 2025-May-31
Inspection Number: 20912123

Inspection Result:

PASS

FACILITY:	METRO TRUCK AND TRAILER REPAIR / S11850	INSP. TYPE:	Complete	INSP. START:	2024-Apr-30 02:00 PM PDT
INSPECTOR:	BAGRI, AMRITPAL / 300086	INSP. CLASS:	Class 3 - Trailer and Semi-Trailer	INSP. COMPLETE:	2024-May-01 08:00 AM PDT
WORK ORDER #:	007328	INSP. REASON:	Annual		

VEHICLE JUR:	British Columbia	REGI:	14360834	VIN:	1JJV532D3RL426406
PLATE #:	65342K	UNIT/FLEET#:	53278	OWNER/LESSEE NAME:	HAPT, HAP TRUCKING LTD
PERMITTED GVW(kg):	0	BODY STYLE:	Van Trailer	ADDRESS:	7954 webster rd, 7954 webster rd Delta, British Columbia V4G1G6, Canada
VEHICLE YEAR:	2024	ODOMETER:			
MAKE:	WABASH	HUB ODOMETER:			
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30L	Automatic	35	35	7.1	7.1	6.4	6.4	
2	Clamp	30L	Automatic	35	35	6.4	6.4	6.4	6.4	
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	45	45	Lining (Shoe)	18	18	Drum	419.27	419.27
2	50	50	Lining (Shoe)	17	18	Drum	419.30	419.30
Comment:			Comment:			Comment:		

Inspection Comments:

Has this Vehicle been road tested? No **Road Test Date:**  **Road Tester:**

Inspector: BAGRI, AMRITPAL **Signature:**

This Inspection Report was submitted to CVSE on 2024-May-01 09:22 AM PDT
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.