

Commercial Vehicle Inspection Report

Decal Number: **GC55807**
 Decal Expiry Date: **2025-May-31**
 Inspection Number: **20912071**

Inspection Result:
PASS

FACILITY: METRO TRUCK AND TRAILER REPAIR / S11850 **INSP. TYPE:** Complete
INSPECTOR: BAGRI, AMRITPAL / 300086 **INSP. CLASS:** Class 3 - Trailer and Semi-Trailer **INSP. START:** 2024-Apr-30 10:00 AM PDT
WORK ORDER #: 007064 **INSP. REASON:** Annual **INSP. COMPLETE:** 2024-May-01 06:00 AM PDT

VEHICLE JUR: British Columbia **REGI:** 14360885 **VIN:** 1JJV532D7RL426408
PLATE #: 65344K **UNIT/FLEET#:** 53280 **OWNER/LESSEE NAME:** HAPT, HAP TRUCKING LTD
PERMITTED GVW(kg): 0 **BODY STYLE:** Van Trailer **ADDRESS:** 7954 webster rd, 7954 webster rd
VEHICLE YEAR: 2024 **ODOMETER:** Delta, British Columbia
WAKE: WABASH **HUB ODOMETER:** V4G1G6, Canada
MODEL: **BRAKE TYPE:** Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30L	Automatic	35	35	6.4	5.6	5.6	5.6	
2	Clamp	30	Automatic	35	35	6.4	5.6	5.6	5.6	

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	42	44	Lining (Shoe)	18	17	Drum	419.33	419.33
2	50	45	Lining (Shoe)	18	18	Drum	419.40	419.40

Inspection Comments:
 Was this Vehicle been road tested? No **Road Test Date:** _____ **Road Tester:** _____
Inspector: BAGRI, AMRITPAL **Signature:** 

This Inspection Report was submitted to CVSE on 2024-May-01 09:06 AM PDT
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.