



Commercial Vehicle Inspection Report

Decal Number: GA26766
Decal Expiry Date: 2024-Nov-30
Inspection Number: 20726357

Inspection Result:
PASS

FACILITY: METRO TRUCK AND TRAILER REPAIR / S11850
INSPECTOR: BAGRI, AMRITPAL / 300086
WORK ORDER #: 005700
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual
INSP. START: 2023-Nov-16 05:28 AM PST
INSP. COMPLETE: 2023-Nov-17 08:15 AM PST

VEHICLE JUR: British Columbia
PLATE #: 68329U
LICENSED GVW(kg): 999999
VEHICLE YEAR: 2018
MAKE: UTILITY
MODEL:
REGI: 12466862
UNIT/FLEET#: 53324
BODY STYLE: Reefer Van Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 1UYVS3532J7420213
OWNER/LESSEE NAME: HAPT, HAP TRUCKING LTD
ADDRESS: 7954 webster rd, 7954 webster rd
Delta, British Columbia
V4G1G6, Canada

Vehicle Identification (VIN) Passed
Section 1 - Power Train Not Applicable
Section 2 - Suspension Repaired (same day) height control valve replaced
Section 3 - Brake System Passed
Section 3A - Air Brakes Repaired (same day) axle 3 right side s-cam replaced
Section 3H - Hydraulic Brakes Not Applicable
Section 4 - Steering Not Applicable
Section 5 - Instruments and Auxiliary Equipment Not Applicable
Section 6 - Lamps Passed
Section 7 - Electrical System Passed
Section 8 - Frame and Body Passed
Section 9A - Tires Repaired (same day) axle 2 left side replaced
Section 9B - Wheels Repaired (same day) axle 1 right side hub seal replaced
Section 10 - Coupling Devices Passed
Section 11 - Other Vehicle Components Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	32	32	8.7	7.9	8.7	9.5	
2	Clamp	30	Automatic	32	33	14.3	14.3	8.7	8.7	
3	Clamp	30	Automatic	33	36	8.7	8.7	9.5	8.7	

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right	
1	70	75	Lining (Shoe)	17	16	Drum	0.00	0.00	
2	55	75	Lining (Shoe)	18	16	Drum	0.00	0.00	
3	75	70	Lining (Shoe)	16	17	Drum	0.00	0.00	

Comment: all dust shield remove

Inspection Comments:
Has this Vehicle been road tested? No
Inspector: BAGRI, AMRITPAL
Road Test Date:
Signature: 
Road Tester:

This Inspection Report was submitted to CVSE on 2023-Nov-17 11:30 AM PST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.