



# Commercial Vehicle Inspection Report

Decal Number: GD39123  
Decal Expiry Date: 2025-Jul-31  
Inspection Number: 21008527

Inspection Result:  
**PASS**

FACILITY: METRO TRUCK AND TRAILER REPAIR / S11850  
INSPECTOR: BAGRI, AMRITPAL / 300086  
WORK ORDER #: 008135  
INSP. TYPE: Complete  
INSP. CLASS: Class 3 - Trailer and Semi-Trailer  
INSP. REASON: Annual  
INSP. START: 2024-Jul-18 12:00 PM PDT  
INSP. COMPLETE: 2024-Jul-19 07:57 AM PDT

VEHICLE JUR: British Columbia  
PLATE #: 01760L  
LICENCED GVW(kg): 999999  
VEHICLE YEAR: 2019  
MAKE: VANGUARD  
MODEL:  
REGI: 12724996  
UNIT/FLEET#: 53326  
BODY STYLE: Van Trailer  
ODOMETER:  
HUB ODOMETER:  
BRAKE TYPE: Air  
FUEL TYPE:  
VIN: 5V8VA53B3KM900011  
OWNER/LESSEE NAME: HAPT, HAP TRUCKING LTD  
ADDRESS: 7954 webster rd, 7954 webster rd  
Delta, British Columbia  
V4G1G6, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) axle 3 right side brake and drum replaced
Section 3A - Air Brakes	Repaired (same day) axle 3 right side maxi soppily air line replaced
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Repaired (same day) axle 3 both side tire replaced
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	36	36	8.7	7.9	7.1	6.4	
2	Clamp	30	Automatic	36	36	10.3	9.5	9.5	10.3	
3	Clamp	30	Automatic	34	34	14.3	14.3	14.3	14.3	

Comment: \_\_\_\_\_

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	65	75	Lining (Shoe)	15	14	Drum	419.78	419.90
2	80	75	Lining (Shoe)	14	15	Drum	419.76	419.70
3	90	25	Lining (Shoe)	14	21	Drum	419.75	419.10

Comment: \_\_\_\_\_

Inspection Comments:  
Has this Vehicle been road tested? No  
Inspector: BAGRI, AMRITPAL  
Road Test Date: \_\_\_\_\_  
Signature:   
Road Tester: \_\_\_\_\_

This Inspection Report was submitted to CVSE on 2024-Jul-19 08:02 AM PDT  
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.