



# Commercial Vehicle Inspection Report

Decal Number: FY76031  
Decal Expiry Date: 2024-Aug-31  
Inspection Number: 20609575

Inspection Result:  
**PASS**

**FACILITY:** SANDHER TRUCK & TRAILER REPAIR LTD. / S15370  
**INSPECTOR:** SANDHU, SIMRANJEET / 300113  
**WORK ORDER #:**

**INSP. TYPE:** Complete  
**INSP. CLASS:** Class 3 - Trailer and Semi-Trailer  
**INSP. REASON:** Annual

**INSP. START:** 2023-Aug-05 10:00 AM PDT  
**INSP. COMPLETE:** 2023-Aug-05 11:30 AM PDT

**VEHICLE JUR:** British Columbia  
**PLATE #:** 78792J  
**LICENCED GVW(kg):** 0  
**VEHICLE YEAR:** 2020  
**MAKE:** HYUNDAI  
**MODEL:**

**REGI:** 13494956  
**UNIT/FLEET#:**  
**BODY STYLE:** Van Trailer  
**ODOMETER:**  
**HUB ODOMETER:**  
**BRAKE TYPE:** Air  
**FUEL TYPE:**

**VIN:** 3H3V533C1LT030004  
**OWNER/LESSEE NAME:** HAP, TRUCKING LTD  
**ADDRESS:** 7954 WEBSTER RD  
Delta, British Columbia  
V4G1G6, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

### Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	33	35
2	Clamp	30	Automatic	34	35
3	Clamp	30	Automatic	33	35
<b>Comment:</b>					

### Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
7.9	7.9	12.7	12.7	
9.5	10.3	9.5	9.5	
6.4	6.4	11.9	11.9	
<b>Comment:</b>				

### Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	40	35
2	35	35
3	40	40
<b>Comment:</b>		

### Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	19	19
Lining (Shoe)	19	19
Lining (Shoe)	19	19
<b>Comment:</b>		

### Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		
<b>Comment:</b> Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

### Inspection Comments:

Has this Vehicle been road tested? No  
**Inspector:** SANDHU, SIMRANJEET  
**Road Test Date:**  
**Road Tester:**  
**Signature:** \_\_\_\_\_

This Inspection Report was submitted to CVSE on 2023-Aug-05 06:45 PM PDT  
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

### NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSE0014

8/5/2023 6:46:16 PM PDT