



# Commercial Vehicle Inspection Report

Decal Number: GD39137  
Decal Expiry Date: 2025-Jul-31  
Inspection Number: 21017926

Inspection Result:  
**PASS**

<b>FACILITY:</b>	METRO TRUCK AND TRAILER REPAIR / S11850	<b>INSP. TYPE:</b>	Complete	<b>INSP. START:</b>	2024-Jul-27 07:00 AM PDT
<b>INSPECTOR:</b>	BAGRI, AMRITPAL / 300086	<b>INSP. CLASS:</b>	Class 3 - Trailer and Semi-Trailer	<b>INSP. COMPLETE:</b>	2024-Jul-27 12:00 PM PDT
<b>WORK ORDER #:</b>	007858	<b>INSP. REASON:</b>	Annual		

<b>VEHICLE JUR:</b>	British Columbia	<b>REGI:</b>	12733649	<b>VIN:</b>	1UYVS253XK3522801
<b>PLATE #:</b>	61792K	<b>UNIT/FLEET#:</b>	53229	<b>OWNER/LESSEE NAME:</b>	HAPT, HAP TRUCKING LTD
<b>LICENCED GVW(kg):</b>	999999	<b>BODY STYLE:</b>	Van Trailer	<b>ADDRESS:</b>	7954 webster rd, 7954 webster rd
<b>VEHICLE YEAR:</b>	2019	<b>ODOMETER:</b>			Delta, British Columbia
<b>MAKE:</b>	UTILITY	<b>HUB ODOMETER:</b>			V4G1G6, Canada
<b>MODEL:</b>		<b>BRAKE TYPE:</b>	Air		
		<b>FUEL TYPE:</b>			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxillary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	36	36	9.5	7.9	9.5	9.5	
2	Clamp	30	Automatic	36	36	8.7	7.9	8.7	7.9	
<b>Comment:</b>						<b>Comment:</b>				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	60	80	Lining (Shoe)	17	15	Drum	419.80	420.13
2	75	75	Lining (Shoe)	14	14	Drum	420.15	420.10
<b>Comment:</b>			<b>Comment:</b>			<b>Comment:</b>		

**Inspection Comments:**  
**Has this Vehicle been road tested?** No **Road Test Date:**  **Road Tester:**  
**Inspector:** BAGRI, AMRITPAL **Signature:**

This Inspection Report was submitted to CVSE on 2024-Jul-27 01:34 PM PDT  
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.