



Commercial Vehicle Inspection Report

Decal Number: GD39147
Decal Expiry Date: 2025-Aug-31
Inspection Number: 21026030

Inspection Result:
PASS


CITY: METRO TRUCK AND TRAILER REPAIR / S11850
SPECTOR: BAGRI, AMRITPAL / 300086
DRK ORDER #: 007891
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual
INSP. START: 2024-Aug-01 12:00 PM PDT
INSP. COMPLETE: 2024-Aug-02 01:00 PM PDT

VEHICLE JUR: British Columbia
PLATE #: 84157K
REGISTERED GVW(kg): 999999
VEHICLE YEAR: 2019
MAKE: UTILITY
MODEL:
REGI: 12733707
UNIT/FLEET#: 53230
BODY STYLE: Van Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 1UYVS2531K3522802
OWNER/LESSEE NAME: HAPT, HAP TRUCKING LTD
ADDRESS: 7954 webster rd, 7954 webster rd
Delta, British Columbia
V4G1G6, Canada

| | |
|---|--|
| Vehicle Identification (VIN) | Passed |
| Section 1 - Power Train | Not Applicable |
| Section 2 - Suspension | Passed |
| Section 3 - Brake System | Passed |
| Section 3A - Air Brakes | Passed |
| Section 3H - Hydraulic Brakes | Not Applicable |
| Section 4 - Steering | Not Applicable |
| Section 5 - Instruments and Auxiliary equipment | Not Applicable |
| Section 6 - Lamps | Passed |
| Section 7 - Electrical System | Passed |
| Section 8 - Frame and Body | Passed |
| Section 9A - Tires | Repaired (same day) axle 1 both side tire replaced |
| Section 9B - Wheels | Passed |
| Section 10 - Coupling Devices | Passed |
| Section 11 - Other Vehicle Components | Not Applicable |

| * Brake Chamber Type, Size and Push Rod Stroke (mm) | | | | | | Tire Tread Depth (mm) | | | | |
|---|-------|------|------------|------|-------|-----------------------|---------|---------|---------|----------|
| Axles | Type | Size | Slack Adj. | Left | Right | Outer L | Inner L | Inner R | Outer R | Steering |
| 1 | Clamp | 30 | Automatic | 35 | 35 | 13.5 | 13.5 | 13.5 | 13.5 | |
| 2 | Clamp | 30 | Automatic | 35 | 36 | 7.1 | 7.1 | 6.4 | 6.4 | |
| Comment: | | | | | | Comment: | | | | |

| * Brake Camshaft Rotation (degrees) | | | Brake Lining/Pad (mm) | | | Rotor Thickness or Drum Inside Diameter (mm) | | |
|-------------------------------------|------|-------|-----------------------|------|-------|--|--------|--------|
| Axles | Left | Right | Lining/Pad | Left | Right | Rotor/Drum | Left | Right |
| 1 | 75 | 70 | Lining (Shoe) | 14 | 14 | Drum | 419.78 | 419.88 |
| 2 | 60 | 25 | Lining (Shoe) | 15 | 21 | Drum | 420.25 | 419.10 |
| Comment: | | | Comment: | | | Comment: | | |

Inspection Comments:
Has this Vehicle been road tested? No
SPECTOR: BAGRI, AMRITPAL
Road Test Date:
Signature: 
Road Tester:

This Inspection Report was submitted to CVSE on 2024-Aug-02 01:51 PM PDT
Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.