



Commercial Vehicle Inspection Report

Decal Number: GD39189
Decal Expiry Date: 2025-Aug-31
Inspection Number: 21053464

Inspection Result:
PASS

FACILITY: METRO TRUCK AND TRAILER REPAIR / S11850
INSPECTOR: BAGRI, AMRITPAL / 300086
WORK ORDER #: 008088
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual
INSP. START: 2024-Aug-28 04:00 PM PDT
INSP. COMPLETE: 2024-Aug-29 07:30 AM PDT

VEHICLE JUR: British Columbia
PLATE #: 21767J
LICENCED GVW(kg): 999999
VEHICLE YEAR: 2018
MAKE: UTILITY
MODEL:
REGI: 12364231
UNIT/FLEET#: 53321
BODY STYLE: Van Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 1UYVS353XJ7347804
OWNER/LESSEE NAME: HAPT, HAP TRUCKING LTD
ADDRESS: 7954 webster rd, 7954 webster rd
Delta, British Columbia
V4G1G6, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) axle 1 and 2 left side brake and drum replaced
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Repaired (same day) 3 marker light replaced
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Repaired (same day) axle 3 left side tire replaced
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	37	36	11.9	11.9	9.5	9.5	
2	Clamp	30	Automatic	36	36	10.3	9.5	10.3	9.5	
3	Clamp	30	Automatic	36	35	10.3	10.3	5.6	5.6	
Comment:				Comment:						

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	25	80	Lining (Shoe)	21	16	Drum	419.10	419.80
2	25	68	Lining (Shoe)	21	17	Drum	419.10	419.85
3	65	85	Lining (Shoe)	17	14	Drum	419.36	420.21
Comment:			Comment:			Comment:		

Inspection Comments:
Has this Vehicle been road tested? No
Inspector: BAGRI, AMRITPAL
Road Test Date: 
Signature: 
Road Tester:

This Inspection Report was submitted to CVSE on 2024-Aug-29 07:45 AMPDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.
The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSOVP at the Commercial Vehicle Safety Enforcement
CVSE0014
8/29/2024 7:45:11 AM PDT