

Commercial Vehicle **Inspection Report**

Decal Number: Decal Expiry Date: Inspection Number:

GD86902 2025-Sep-30 21066064

Inspection Result:

METRO TRUCK AND TRAILER FACILITY:

BAGRI, AMRITPAL / 300086

INSP. TYPE: INSP. CLASS:

Class 3 - Trailer and Semi-Trailer

INSP. COMPLETE:

INSP. START:

2024-Sep-09 02:00 PM PDT 2024-Sep-10 06:00 AM PDT

INSPECTOR:

WORK ORDER #:

VEHICLE JUR:

REPAIR / S11850

British Columbia

007104

INSP. REASON:

REGI:

Not Applicable

Not Applicable

Left

37

36

Slack Adj.

Automatic

Automatic

13493082

Complete

Annual

Air

VIN:

3H3V532C2MT088013

LICENCED GVW(kg): 0 VEHICLE YEAR:

2021

70449J

UNIT/FLEET#: **BODY STYLE:** 53259 Van Trailer OWNER/LESSEE NAME: ADDRESS:

HAPT, HAP TRUCKING LTD 7954 webster rd, 7954 webster rd

Delta, British Columbia V4G1G6, Canada

MAKE: MODEL:

PLATE #:

HYUNDAI

HUB ODOMETER: BRAKE TYPE:

FUEL TYPE:

ODOMETER:

Vehicle Identification (VIN) Passed Not Applicable Section 1 - Power Train Passed Section 2 - Suspension Section 3 - Brake System Passed Section 3A - Air Brakes Passed Not Applicable Section 3H - Hydraulic Brakes Not Applicable Section 4 - Steering

Section 5 - Instruments and Auxillary Equipment

Section 6 - Lamps Section 7 - Electrical System Section 8 - Frame and Body Passed Section 9A - Tires Passed Section 9B - Wheels Passed Section 10 - Coupling Devices Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Size

30

30

Section 11 - Other Vehicle Components

Туре

Clamp

Clamp

Tire Tread Depth (mm)

	, ,			
Outer L	Inner L	Inner R	Outer R	Steering
12.7	12.7	13.5	13.5	
12.7	11.9	9.5	14.3	
Comment:				

2 Comment:

Axles

Air Brake Camshaft	r Brake Camshaft Rotation (degrees)		
Axles	Left	Right	
1	55	55	
2	50	35	
Comment:			

Left	Right
	~
17	17
16	18

Right

36

36

Rotor Thickness or Drum Inside Diameter (mm)						
Rotor/Drum	Left	Right				
Drum	419.80	419.85				
Drum	419.84	419.55				
Comment:						

Inspection Comments:

Has this Vehicle been road tested? Inspector:

BAGRI, AMRITPAL

No

Road Test Date:

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2024-Sep-10 07:05 AM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.