



Commercial Vehicle Inspection Report

Decal Number: **FW28002**
 Decal Expiry Date: **2023-Nov-30**
 Inspection Number: **20333018**



Inspection Result:
PASS

Facility: MOGATRUCK REPAIR / S5914
 Inspector: BRAR, HARJIT SINGH / 110837
 Work Order Number: 13365

Inspection Type: Complete
 Inspection Class: Class 3 - Trailer and Semi-Trailer
 Inspection Reason: Annual

Inspection Start Date/Time: 2022-Nov-23 08:00 AM
 Inspection Complete Date/Time: 2022-Nov-24 06:00 PM

Vehicle Jurisdiction: British Columbia
 Registration Number: 12364254
 VIN: 1UYVS2537J7349813
 Plate Number: 26440K
 Licenced GVW (kg): 999999
 Vehicle Year: 2018
 Make: UTILITY

Brake Type: Air
 Fuel Type:
 Odometer:
 Hub Odometer:
 Body Style: Van Trailer
 Model:
 Unit/Fleet Number: 53219

Owner/Lessee Name: HAP, Hap Enterprises Ltd
 Address: 7954 WEBSTER RD
 City: Surrey
 Province/State: British Columbia
 Postal Code/ZIP: V4G1G6
 Country: Canada

| | Result | Comment |
|---|----------------|---------|
| Vehicle Identification (VIN) | Passed | |
| Section 1 - Power Train | Not Applicable | |
| Section 2 - Suspension | Passed | |
| Section 3 - Brake System | Passed | |
| Section 3A - Air Brakes | Passed | |
| Section 3H - Hydraulic Brakes | Not Applicable | |
| Section 4 - Steering | Not Applicable | |
| Section 5 - Instruments and Auxillary Equipment | Not Applicable | |
| Section 6 - Lamps | Passed | |
| Section 7 - Electrical System | Passed | |
| Section 8 - Frame and Body | Passed | |
| Section 9A - Tires | Passed | |
| Section 9B - Wheels | Passed | |
| Section 10 - Coupling Devices | Passed | |
| Section 11 - Other Vehicle Components | Not Applicable | |

Air Brake Chamber Type, Size and Push Rod Stroke Measurements (mm)

| Axles (front) | Type | Size | Slack Adj. | Left | Right |
|---------------|-------|------|------------|------|-------|
| 1 | Clamp | 30 | Automatic | 34 | 34 |
| 2 | Clamp | 30 | Automatic | 35 | 35 |

Tire Tread Depth (mm)

| Axles (front) | Outer Left | Inner left | Inner Right | Outer Right | Steering Axle? |
|---------------|------------|------------|-------------|-------------|----------------|
| 1 | 7 | 7 | 7 | 7 | |
| 2 | 8 | 8 | 8 | 8 | |

Comment:

Comment:

Air Brake Camshaft Rotation Measurement (degrees)

| Axles (front) | Left (degrees) | Right (degrees) |
|---------------|----------------|-----------------|
| 1 | 55 | 55 |
| 2 | 60 | 60 |

Brake Lining/Pad Measurement (mm)

| Axles (front) | Lining/Pad | Left | Right |
|---------------|---------------|------|-------|
| 1 | Lining (Shoe) | 17 | 17 |
| 2 | Lining (Shoe) | 16 | 16 |

Rotor Thickness or Drum Inside Diameter Measurement (mm)

| Axles (front) | Rotor/Drum | Left | Right |
|---------------|------------|--------|--------|
| 1 | Drum | 421.00 | 421.00 |
| 2 | Drum | 420.00 | 420.00 |

Comment:

Comment:

Comment:

Inspection Comments:

Has this Vehicle been road tested? No Yes When? _____ Name of the person who did the road test: _____

Inspector Name: BRAR, HARJIT SINGH

Signature: 

This Inspection Report was submitted to CVSE on 2022-Nov-28 11:36 AM

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/MIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

11/28/2022 11:36:41 AM