



# Commercial Vehicle Inspection Report

Decal Number: FS22618  
Decal Expiry Date: 2023-Mar-31  
Inspection Number: 20030247

Inspection Result: **PASS**

Facility: MOGATRUCK REPAIR / S5914      Inspection Type: Complete      Inspection Start Date/Time: 2022-Mar-09 03:00 PM  
Inspector: BRAR, HARJIT SINGH / 110837      Inspection Class: Class 3 - Trailer and Semi-Trailer      Inspection Complete Date/Time: 2022-Mar-09 06:00 PM  
Work Order Number: 11211      Inspection Reason: Annual

Vehicle Jurisdiction: British Columbia      Brake Type: Air      Owner/Lessee Name: HSBC BANK CANADA, Hap Trucking Ltd  
Registration Number: 12926339      Fuel Type:      Address: 7954 Webster Rd  
VIN: 1UYYS2532K7730907      Odometer:      City: Surrey  
Plate Number: 09804J      Hub Odometer:      Province/State: British Columbia  
Licenced GVW (kg): 0      Body Style: Van Trailer      Postal Code/ZIP: V4G1G6  
Vehicle Year: 2019      Model:      Country: Canada  
Make: UTILITY      Unit/Fleet Number: 53240

OK

	Result	Comment
VIP	Passed	
Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Not Applicable	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Not Applicable	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Passed	

### Air Brake Chamber Type, Size and Push Rod Stroke Measurements (mm)

Axles (front)	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	32	32
2	Clamp	30	Automatic	32	32

Comment:

### Tire Tread Depth (mm)

Axles (front)	Outer Left	Inner left	Inner Right	Outer Right	Steering Axle?
1	11	11	10	11	
2	10	10	10	11	

Comment:

### Air Brake Camshaft Rotation Measurement (degrees)

Axles (front)	Left (degrees)	Right (degrees)
1	65	65
2	60	60

Comment:

### Brake Lining/Pad Measurement (mm)

Axles (front)	Lining/Pad	Left	Right
1	Lining (Shoe)	16	16
2	Lining (Shoe)	17	17

Comment:

### Rotor Thickness or Drum Inside Diameter Measurement (mm)

Axles (front)	Rotor/Drum	Left	Right
1	Drum	421.00	421.00
2	Drum	420.00	420.00

Comment:

### Inspection Comments:

Has this Vehicle been road tested? No      When?      Name of the person who did the road test:

Inspector Name: BRAR, HARJIT SINGH

Signature:

This Inspection Report was submitted to CVSE on 2022-Mar-11 06:33 PM

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

### NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/MP at the Commercial Vehicle Safety Enforcement

CVSE0014

3/11/2022 6:33:41 PM

104233