



# Commercial Vehicle Inspection Report

Decal Number: **FS83089**  
 Decal Expiry Date: **2023-Jun-30** *2022-DEC-31PASS*  
 Inspection Number: **20141811**

Facility: METRO TRUCK AND TRAILER REPAIR / S11850  
 Inspector: BAGRI, AMRITPAL / 300086  
 Work Order Number: 003234  
 Inspection Type: Complete  
 Inspection Class: Class 2 - Heavy Vehicle with LGW 5501 kg or more  
 Inspection Reason: Semi-annual  
 Inspection Start Date/Time: 2022-Jun-11 08:11 AM  
 Inspection Complete Date/Time: 2022-Jun-11 04:11 PM

Vehicle Jurisdiction: British Columbia  
 Registration Number: 12846915  
 VIN: 1XPBD49X5KD604030  
 Plate Number: 47775P  
 Licensed GVW (kg): 47000  
 Vehicle Year: 2019  
 Make: PETERBILT  
 Brake Type: Air  
 Fuel Type: Diesel  
 Odometer: 740476 KM  
 Hub Odometer:  
 Body Style: Truck Tractor  
 Model:  
 Unit/Fleet Number: 721  
 Owner/Lessee Name: HAP, HAP TRUCKING LTD.  
 Address: 7954 WEBSTER RD  
 City: Delta  
 Province/State: British Columbia  
 Postal Code/ZIP: V4G 1G6  
 Country: Canada

Result	Comment
Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Repaired (same day)
Section 3 - Brake System	Repaired (same day)
Section 3A - Air Brakes	Repaired (same day)
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day)
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

**Air Brake Chamber Type, Size and Push Rod Stroke Measurements (mm)**

Axles (front)	Type	Size	Slack Adj.	Left	Right
1	Clamp	24L	Automatic	32	32
2	Clamp	30L	Automatic	33	33
3	Clamp	30L	Automatic	33	33

Comment:

**Tire Tread Depth (mm)**

Axles (front)	Outer Left	Inner left	Inner Right	Outer Right	Steering Axle?
1	13			14	✓
2	25	25	11	12	
3	11	10	10	12	

Comment:

**Air Brake Camshaft Rotation Measurement (degrees)**

Axles (front)	Left (degrees)	Right (degrees)
1	40	60
2	50	55
3	30	30

Comment:

**Brake Lining/Pad Measurement (mm)**

Axles (front)	Lining/Pad	Left	Right
1	Lining (Shoe)	17	15
2	Lining (Shoe)	16	16
3	Lining (Shoe)	21	21

Comment:

**Rotor Thickness or Drum Inside Diameter Measurement (mm)**

Axles (front)	Rotor/Drum	Left	Right
1	Drum	0.00	0.00
2	Drum	0.00	0.00
3	Drum	419.10	419.10

Comment:

Inspection Comments:  
 Has this Vehicle been road tested? No When? Name of the person who did the road test:  
 Inspector Name: BAGRI, AMRITPAL Signature:

This Inspection Report was submitted to CVSE on 2022-Jun-11 05:18 PM

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

**NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.**

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/MSP at the Commercial Vehicle Safety Enforcement